

Sinetech (Pty) Ltd.

Tel: (++27) 11 886-7874

Fax: (++27) 11 787-0178 2 Samantha Street, Strijdom Park, Randburg, Johannesburg P O Box 2441, Randburg, South Africa, 2125

Email: sales@sinetech.co.za http://www.sinetech.co.za

Battery Returns Policy

Please Note: The manufacturer's defect warranty only covers manufacturing defects and does not cover incorrect use or abuse.

Case 1: Battery Purchased Less than One Year Ago.

If the battery was purchased less than one year ago and still falls within the one-year Manufacturer's defect warranty, the first initial battery assessment will be done free of charge. Should the client want to have a full battery test conducted together with a test report the cost will be as follows:

- FREE OF CHARGE should the test results show the damage to the battery does fall under the Manufacturer's defect warranty.
- R 500.00 excluding vat, per set of 4 batteries should the test results show the damage to the battery does not fall under the Manufacturer's defect warranty and was as a result of incorrect use or abuse (if less than 4 batteries the same cost applies).

Case 2: Battery Purchased More than One Year Ago.

If the battery was purchased more than one year ago and does not fall within the one-year Manufacturer's defect warranty, the cost will be as follows:

- R 500.00 excluding vat, per set of 4 batteries, for an initial assessment which must be paid upfront before the batteries will be accepted at the dispatch / delivery area (if less than 4 batteries the same cost applies). The initial assessment can only indicate an approximated state of health upon arrival.
- R 1 500.00 excluding vat, per set of 4 batteries, for a full battery test conducted together with a test report which must be paid upfront before the batteries will be accepted at the dispatch / delivery area. A full battery test involves cycling the battery and gives a far more accurate indication as to what the state of health of the battery is (if less than 4 batteries the same cost applies).

Please note: A full battery test will take a minimum of 4 working days.

Policy Created By:

Chris Rodgers

CEO

Reg No: 2015/279933/07

VAT No. 459 015 7972

Executive Directors: C. Rodgers (CEO)

Non Executive Directors: M.M. du Preez, O.J. Goosen, L.F. Walters, M. Jurgens (Alt)